

Date: 03/21/18	Author: Randy Rohr
Product: LaserWash® <input checked="" type="checkbox"/> 4000 <input type="checkbox"/> G5 <input checked="" type="checkbox"/> M5 <input checked="" type="checkbox"/> 360 Plus <input checked="" type="checkbox"/> AutoXpress™ ProTouch® <input checked="" type="checkbox"/> Tandem™ <input checked="" type="checkbox"/> ICON™ <input type="checkbox"/> Access® <input type="checkbox"/> MaxAir®	
Product Serial No:	
Code: 5 - Notice of new products or product changes (no action required).	
Subject: Pushbutton Obsolescence	

The current Siemens line of pushbuttons and operators will be going obsolete in the near future. PDQ will be replacing these components with the new Siemens Innovation line of components.

The system stop assembly part numbers 11010113 and 11010173 used for the Tandem, LaserWash and Icon will require these new pushbutton part numbers as replacements in the event of a failure. The replacement part number can be found on the 11010113rev03 PPC and 11010173rev04 PPC. The LaserWash 4000 joy stick control box part number M104301 is also affected with this change. The new components can be found on the M104301rev11 PPC drawing. Note that these new pushbuttons and contact blocks are not compatible with the current version. Therefore, after this change, when a pushbutton is replaced in the field the contact block must also be replaced.

Parts and Assemblies:

Description	Part Number	QTY
See attached Pictorial Parts Catalog pages		